

TeeJet 845-AB

Contact TeeJet Customer Service/Repair or OEM to get instructions for updating.

TeeJet 845-AB v1.22

September 2025

Associated Documentation:

Manual 98-05364 R1

User Guide 98-01611 R1

OEM Reference Guide 98-01612 R0

Fixes:

- Maximum Pressure Reference setting limit changed to 99.9 bar
- Maximum Flow Reference setting limit changed to 499.9 liters / minute
- Flowmeter Calibration counter limit changed to 9,999,999 pulses.
- Issue with using US units while using Pressure Regulation, resolved.

TeeJet 845-AB v1.21

April 2024

Associated Documentation:

- Manual 98-05364 R0
- User Guide 98-01611 R0
- OEM Reference Guide 98-01612 R0

Fix:

- Tank size restriction issue, resolved.

TeeJet 845-AB v1.20

October 2023

Associated Documentation:

- Manual 98-05364 R0
- User Guide 98-01611 R0
- OEM Reference Guide 98-01612 R0

Fixes:

- Pressure Mode Regulation reference issue, resolved.
- Volume counting incorrectly, resolved.
- Automatic Flow Calibration issue, resolved.

TeeJet 845-AB v1.10

April 2023

Associated Documentation:

- Manual 98-05364 R0
- User Guide 98-01611 R0
- OEM Reference Guide 98-01612 R0

Fix:

- Changed Minimum Regulation Voltage range to 0-12V.

TeeJet 845-AB v1.00

February 2023

Associated Documentation:

- Manual 98-05364 R0
- User Guide 98-01611 R0

TeeJet 845-AB



- OEM Reference Guide 98-01612 R0

Initial Release:

- Replacement for the TeeJet 844-AB
- Updated LCD display is backlit and easier to read than previous models.



English-US

© TeeJet Technologies 2025

www.teejet.com

A Subsidiary of  **Spraying Systems Co.**